

From: "Perkins, Brandon" <Perkins.Brandon@epa.gov>
To: "Perkins, Brandon" <Perkins.Brandon@epa.gov>
Date: 9/25/2019 12:37:38 PM
Subject: FW: Gunshy Aerial Photos
Attachments: [ATT00001.txt](#)
[Aerial Photos from 1965 to 1990.pdf](#)

Brandon Perkins | Site Assessment Manager
Superfund & Emergency Management Division
United States Environmental Protection Agency | Region 10
1200 Sixth Ave Suite 155 (Mail Stop: 13-J07)
Seattle, WA 98101
P: (206) 553-6396
Email: perkins.brandon@epa.gov

From: Ader, Linda <LAder@ene.com>
Sent: Wednesday, September 25, 2019 9:57 AM
To: Perkins, Brandon <Perkins.Brandon@epa.gov>
Subject: RE: Gunshy Sample Locations

Linda Ader, START-IV Site Assessment Team Leader

(b)
Cell: (b) (6)
LAder@ene.com • www.ene.com

From: Perkins, Brandon <Perkins.Brandon@epa.gov>
Sent: Wednesday, September 25, 2019 9:26 AM
To: Ader, Linda <LAder@ene.com>
Subject: Gunshy Sample Locations

Hi Linda

Got your message regarding Gunshy. Here are the locations of the three wells:

- Arthur Johnson Park □ Attached an email from the City of Redmond that includes a map of their monitoring wells in the area. The two southern wells will be included in the PA sampling.
- Residential property – I believe this is also a monitoring well. It is located at (b) (6) Redmond, WA. Attached the corresponding well log.

We'll need to chat a bit about the on-site borings. Reports indicate the fill went in to the Thompson Hay Field. Highlighting that area in the attached Google Earth screenshot. I'm in training today but can give you a call when we have a break.

I've also attached the citizen's complaint about the fill alleged to be contaminated. The attached Oct 10th letter from the property owner also includes information about the fill area.



Brandon Perkins | Site Assessment Manager
Superfund & Emergency Management Division
United States Environmental Protection Agency | Region 10
1200 Sixth Ave Suite 155 (Mail Stop: 13-J07)
Seattle, WA 98101
P: (206) 553-6396
Email: perkins.brandon@epa.gov